

M2222 / SPAKM2222 — Gasket Rework

QUICK FACTS:	
Part Numbers	M2222, SPAKM2222
Issue	Poor dispersion — improper compound mixing
Completed affected Stock Identified By	Blue sticker on outside of box
In-House Stock Completed	March 18, 2025
Field Action Required	Return affected stock for rework
Contact	Ryan Mirabito — rmirabito@premiumguard.com

- PGI has identified a potential defect in a specific production batch of the M2222 and SPAKM2222. The gasket compound was not properly mixed during manufacturing, which may cause the gasket to delaminate.
- This condition does not affect every unit within the date range. We have calculated potential 0.0007% observed failure rate; however, as a proactive quality measure, PGI is replacing the gaskets on all units produced within the affected batch.
- All in-house inventory has been reworked as of March 18, 2026. Reworked units are identified by a blue sticker on the outside of the box. No further action is required for these units.



Reworked M2222 unit — blue sticker on box confirms gasket has been replaced.

Part Number	Date Code
M2222	25MLA28C 13786
M2222	25MRO17C 13786
M2222	25MYF11 13786
M2222 & SPAKM2222	25MEJ30C 13786
M2222 & SPAKM2222	25MRO08C 13786
M2222 & SPAKM2222	25MYM23C 13786
M2222 & SPAKM2222	25MYUJ22C 13786
M2222 & SPAKM2222	26MYJ09C 13786
SPAKM2222	25MEJ21C 13786
SPAKM2222	25MLA29C 13786
SPAKM2222	25MRN19C 13786
SPAKM2222	25MRN24C 13786
SPAKM2222	25MYF12 13786
SPAKM2222	26MYJ14C 13786
SPAKM2222	26MYJ15C 13786

All listed date codes must be returned, with or without a “C”.



3604 Wilder Rd
Bay City, MI 48706
Website: www.rowleys.com
www.facebook.com/Rowleys.Wholesale
Email: customerservice@rowleys.com

Toll Free: 1-800-ROWLEYS
(769-5397)
Phone: 989-671-6500
Fax: 989-671-1400

**BAY CITY, MI • MEDINA, OH
SOUTHGATE, MI • COLUMBUS, OH**